

DAILY SERVICE DELIVERY OVERVIEW

TUESDAY, APRIL 26, 2011

1. RUNS PULLED OUT- IN SERVICE:

	SCHEDULED	% PULLED OUT IN SERVICE	NOT OUTS	RUNS WORKED AT OVER TIME
SYSTEM WIDE	1174	95.6%	52	59

2. VEHICLES AVAILABILITY

	SCHEDULED	AVAILABLE	SPARE RATIO
LRV	114	112	-2%
F-LINE	18	22	22%
CABLE CAR	26	29	12%
WOODS	140	166	19%
KIRKLAND	111	122	10%
FLYNN	103	108	5%
POTRERO 40'	44	49	11%
POTRERO 60'	47	34	-28%
PRESIDIO	98	105	7%
TOTAL	701	754	8%

3. OPERATORS' ABSENTEEISM:

	Scheduled WF	Total Unavailable	Sick	Vacation	Unplanned Leave	Other Reasons
Green	201	53	5	11	17	20
Cable Car	109	27	3	6	15	3
Potrero	230	55	11	5	28	11
Presidio	196	36	4	9	17	6
Kirkland	221	35	11	5	15	4
Woods	330	87	18	14	42	13
Flynn	202	36	8	7	13	8
TOTAL	1,489	329	60	57	147	65

1. ACCIDENTS & DELAYS > 20 MINUTES:

ACCIDENTS

TIME DATE	CALL FROM DIVISION	TO CC	OP#	RUN	LINE	VEH	LOCATION	NATURE OF OCCURRENCE ACTION TAKEN	DELAY			
									DI	START	END	CC
12:34 04/26/11	R OPERATOR FL	35	1811	439	38L	6286	GEARY BETWEEN 8TH AVE & 9TH AVE (IB)	ACCIDENT (COACH / TRUCK) H/R NO INJURY	IB	12:34	14:25	26
							1167163					
14:06 04/26/11	R OPERATOR PR	25	3577	043	21	5622	SCHRADER & FULTON (OB)	ACCIDENT (COACH / AUTO), H/R	OB	13:56	15:00	26
							1167245					

ACCIDENTS & DELAYS > 20 MINUTES - CONTINUED:

ACCIDENTS

17:20 04/26/11	R	OPERATOR FL	26	2479	510	8X	6265	BAYSHORE BETWEEN ARLETA & RAYMOND (OB)	ALLEGED VEHICLE ACCIDENT COACH / AUTO ON 101 SOUTH FREEWAY NEAR SILVER AVENUE EXITS. (PASSENGER TOLD OPERATOR EMERGENCY HATCH FLEW OFF COACH.)	OB	17:20	18:37	33
							1167267	INSP H. VONG RESPONDED, SS*, 6-A-46*, VIDEO* NO INJURIES, NO 799. VEH DELAY: 01:17					

LINE DELAY > 20 MINUTES

TIME DATE	CALL FROM DIVISION	To CC	OP#	RUN	LINE	VEH	LOCATION	NATURE OF OCCURRENCE ACTION TAKEN	DELAY				
									DI	START	END	CC	
04:40 04/26/11	T	SFPD	77				FULTON BETWEEN 36TH AVE & 38TH AVE (IB,OB)	VEHICLE FIRE	IB	04:40		18	
							1167170	INSP A VELACRUZ RESP, REROUTE IB/OB LINE DELAY: 00:43		LD	04:40	05:23	
14:00 04/26/11	R	CCO OBSERVED ME	23				DUBOCE JUNCTION (OB)	SWITCH D-1 DISTURBED; UNABLE TO SET FOR DIVERGE MOVE	OB	14:00		83	
							1167264	SIGNAL 501 CLEARED. 86/J/1538, 9/J/1545, 39/J/1519 ROUTE CHANGE TO K OUTBOUND; 60/J/1455 CHANGE TO CASTRO SHUTTLE; 14/N/1403-1532 S/B OB TO IB AT CASTRO. LINE DELAY: 00:42		LD	14:00	14:42	